

I believe the cost that you reflect are not accurate and that in fact will be much higher. The cost of hydros with eddy current inspections in south Florida is around \$25.00. I wonder how you arrived at your cost estimate.

There is also reference to additional fill procedures for these tanks with no information on what the procedures would be.

I do agree that these tanks must be eddy current tested to continue using them, but I believe that the better solution is to discontinue their use in high pressure service.